

1993 Toyota Townace Wagon 4-door  
Royal Lounge Limited Edition



Scale

- 1 - 2 Poor condition
- 3 Fair condition
- 4 - 5 Excellent Condition

Car Detail

Engine Capacity 1998 cc	Mileage 137805 km	Fuel Petrol	Inspection Date 10-011-2024
Chassis No YR21-0130415	Model Code E-YR21G	Color Silver	Location Japan
Transmission AT	Drive Type 2WD	No of Doors 4	No of Seats 7

Engine / Transmission 63%

Parameter	Comment	Points
Engine	The engine is in good condition with only minor wear.	4
Battery	The battery is functional but shows signs of aging. Regular testing is recommended.	3
Engine Oil Level Dipstick	The dipstick shows an adequate oil level, but the oil appears slightly discolored.	3
Coolant	The cooling system is performing well with no signs of contamination.	4
Exhaust Smoke	The exhaust emits a moderate amount of smoke, which may indicate minor issues.	3
Gear Shifting	The exhaust emits a moderate amount of smoke, which may indicate minor issues.	2

Steering, Suspension & Brakes 80%

Parameter	Comment	Points
Steering	The steering is smooth with only slight wears present.	4
Suspension	The suspension is in good condition, providing a comfortable and stable ride with only minor signs of wear.	4
Brakes	The brakes are in good condition, providing solid stopping power with slight wear on the pads.	4

Air Conditioning 70%

Parameter	Comment	Points
AC Cooling	The AC cooling is good on all levels. A routine check is recommended.	4
Heater	The heater is working but takes a longer than usual time to reach the desired temperature. A checkup is recommended.	3

Electricals / Interiors 80%

Parameter	Comment	Points
Power Windows	The power windows work smoothly, with just a bit of noise occasionally.	4
Airbags	The airbags are in good condition, with no visible signs of damage or wear.	4
Electricals	The electrical system is in good condition, with all major components functioning properly.	4

Exterior / Tyres 72%

Parameter	Comment	Points
Pillar Right C	The right C-pillar shows some wear, including minor dents or scratches, but remains structurally sound.	3
Running Border Left	The left running board shows some signs of wear, including scratches or minor dents, but remains functional.	3
Running Border Right	The right running board is in excellent condition, showing no signs of wear or damage.	5
Left Quarter Pane	The left quarter panel is in good condition with only minor cosmetic imperfections.	4
Right Quarter Pane	The right quarter panel shows some visible signs of wear. Some cosmetic repairs are recommended.	3

Vehicle Pictures

